

	M4x0.5		C4.6.7
	M4x0.5		C4.8.7
	M4x0.5		C4.6.8
	M4x0.5		C4.6.9
	M4x0.5		C4.8.8
	M6		C6.10
	M8		C8.12
	M6		CK6.20
	M8		CK8.23
	M10		CK10.30

<b>Гайки</b>	
	G4.160
	G4.220
	G4.275
	G4.410

Базировочные элементы

	M5		Винт T5.10
	M5		Винт T5.12
	V5.12		Шайба T5.14
	M5		Втулка T8.14

Ключи

T	F
T9	2.5
T15	3.2
T20	4


  

Обозначение	S
S2.5	2.5
S3	3
S4	4
S5	5
S6	6



**Стакан**



Вращение:  
левое      правое




Пример обозначения:

Обозначение	d	D	H	Вращение
СТ32x60x100	32	60	100	правое
СТ32x60x100ЛH	32	60	100	левое


**Клинья**




Обозначение	L
K01.004	4




Обозначение	L
K01.007	7
K01.010	8
K01.012	10
K01.015	13
K01.020	17
K01.15.020	20




Обозначение	L
K01.030	27
K01.040	37
K01.050	47
K01.060	57



Обозначение	L
K01.080	77
K01.100	97
K01.120	117



K01.15.030



K01.15.050




Обозначение	L
K50.040	40
K50.050	50
K50.060	60
K50.080	80
K50.100	100

Обозначение	L
K50.120	120
K50.130	130
K50.150	150
K50.180	180
K50.230	230




Обозначение	L
K60.100	100
K60.120	120
K60.130	130

Обозначение	L
K60.150	150
K60.180	180
K60.230	230




Обозначение	L
K70.040	40
K70.060	60
K70.080	80

Обозначение	L
K70.100	100
K70.130	130
K70.150	150



Обозначение	L
K06.25.01	36
K06.26.01	43



Обозначение	L
K06.27.01	31